



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	19,478.4	TSO:	0.0	W/O#:	12033
PCE:	PC0608	CSN:	34,374	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA57A676	10,892	8,108
Disk, 2 nd Stg.	3013712	6Y735	17,669	6,331
Disk, 3 rd Stg.	3011713	3Y729	17,669	7,331
Impeller	3027798	TXA1A9511	10,905	8,095
Disk, CT	3013411	YUAA007A387	11,841	4,159
PT Disk, 1 st Stg.	3026812	6B873	11,883	8,117

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	TBA	0.0
FUEL PUMP	702801-5	TBA	0.0
FUEL CONTROL UNIT	3244897-4	C66319	383.5
FLOW DIVIDER	25536-4/3019906	TBA	0.0
OIL/FUEL HEATER	10552E/3032710	TBA	0.0
COMP. BLEED VALVE	3049038-03	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.