



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	GG:6,943.9 PS: 6,943.9	TSO:	GG: 1,444.2 PS: 0.0	W/O#:	9441
PCE:	PH0080	CSN:	NA	CSO:	NA	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	41B629	4,328	14,672
Disk, 2 nd Stg.	3013712	45B415	7,744	16,256
Disk, 3 rd Stg.	3011713	45B391	6,983	18,017
Impeller	3013176	9F221	5,647	13,353
Disk, CT	3013411	A002B1EL	9,317	6,683
PT Disk, 1 st Stg.	3026812	YUAA012A136	19,893	4,107
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	TBA	TBA	0.0
FUEL PUMP	386101-5	0619	1,444.2
FUEL CONTROL UNIT	3244786-6	C22154	1,444.2
START FLOW CONTROL	25234-5	15095	1,444.2
OIL/FUEL HEATER	10552E	243	1,444.2
COMP. BLEED VALVE	3100829-03	52A542	1,444.2
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.