



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-41	TSN:	7,896.8	TSO:	0.0	W/O#:	TBA
PCE:	RC0028	CSN:	8,234	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3041501	61B132	8,234	21,766
Disk, 2 nd Stg.	3023112	A0005146	8,234	11,766
Disk, 3 rd Stg.	3011713	A0005152	8,234	11,766
Impeller	3036793	4H758	8,234	15,766
Disk, CT	3049291-01	A0005E56	8,234	1,766
PT Disk, 1 st Stg.	3029312	A0005YD7	8,234	21,766
PT DISK, 2 nd Stg.	3029313	A0005Y5C	8,234	21,766
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-007-01	TBA	0.0
FUEL PUMP	025323-300-03	7326	0.0
FUEL CONTROL UNIT	3244755-22-21-18	A45933	0.0
FLOW DIVIDER	3019906	14351	0.0
OIL/FUEL HEATER	10585K	WA20277	0.0
LP COMP. BLEED VALVE	3123123-01	AHX000379	0.0
HP COMP. BLEED VALVE	3123122-01	30A839	0.0
Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.			

Comments: All engines ship FOB ATS dock.