



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	4,792.8	TSO:	2,189.7	W/O#:	11831
PCE:	PH0878	CSN:	Starts: 3,061 Flights: 9,980	CSO:	Starts: 1,608 Flights: 4,620	TSHS:	60.1

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1D627	16,749	2,251
Disk, 2 nd Stg.	3013712	A00061TA	19,308	4,692
Disk, 3 rd Stg.	3011713	A00050X0	19,297	5,703
Impeller	3013176	A6680	16,861	2,139
Disk, CT	3013411	4H054	14,950	1,050
PT Disk, 1 st Stg.	3026812	A000118C	18,441	5,559
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002	2455315	2,189.7
FUEL PUMP	386101-5	003674	2,189.7
FUEL CONTROL UNIT	4138008-3	C21042	60.12
FLOW DIV/DUMP VALVE	3019906/25536-4	9959559154	2,189.7
OIL/FUEL HEATER	10552E	WA32124	2,189.7
COMP. BLEED VALVE	3100829-03	19A825	2,189.7
Key: TBA = To be assigned, N/A = Not Applicable			

Comments: All engines ship FOB ATS dock.