



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-27/28</b>	TSN:	GG: 7,814.8 PS: 8,044.8	TSO:	GG: 1,805.8 PS: 2,035.8	W/O#:	<b>6625</b>
PCE:	<b>50145</b>	CSN:	GG: 8,891 PS: 9,002	CSO:	GG: 2,882 PS: 2,993	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	1963	8,891	10,109
Disk, 2 <sup>nd</sup> Stg.	3013712	4803	8,891	15,109
Disk, 3 <sup>rd</sup> Stg.	3011713	3403	8,891	16,109
Impeller	3013176	A0220	8,891	10,109
Disk, CT	3013411	6186	8,891	7,109
PT Disk, 1 <sup>st</sup> Stg.	3012812	7469	9,002	10,998

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AD	1704332AD	2,035.8
START FLOW CONTROL	SFC113	6538	1,805.8
FUEL PUMP	025323-101	13151	1,081.0
FUEL CONTROL UNIT	2524440-5	A7558	UNKNOWN
OIL/FUEL HEATER	10552E	WA6702	1,805.8
COMP. BLEED VALVE	3024060	949	1,805.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.