



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	7,516.6	TSO:	1179.2	W/O#:	6626
PCE:	50945	CSN:	7,634	CSO:	1297	TSHS:	206.8

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	0A0131	7634	11366
Disk, 2 nd Stg.	3013712	0A1909	7634	16366
Disk, 3 rd Stg.	3011713	0B1596	7634	17366
Impeller	3013176	0A8310	7634	11366
Disk, CT	3013411	A7952	12785	3215
PT Disk, 1 st Stg.	3022412	0A3948	7634	12366

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003-01	1148680	1179.2
FUEL PUMP	025323-101-02	3667	1179.2
FUEL CONTROL UNIT	2524440-7-6	304758	1179.2
START FLOW CONTROL	25234-2	8450	1179.2
OIL/FUEL HEATER	10552E	2210	1179.2
COMP. BLEED VALVE	3100829-03	7A35	1179.2

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.