



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-135	TSN:	7,870.4	TSO:	0.0	W/O#:	6285
PCE:	92218	CSN:	6,210	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	8E993	6,210	12,790
Disk, 2 nd Stg.	3013712	8E878	6,210	17,790
Disk, 3 rd Stg.	3011713	8E436	6,210	18,790
Impeller	3013176	1B523	6,210	12,790
Disk, CT	3024211	9D078	6,210	9,790
PT Disk, 1 st Stg.	3022312	7E618	6,210	23,790

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003R	1704267	0.0
FUEL PUMP	025323-101	2114	0.0
FUEL CONTROL UNIT	3244777-4-3	A89466	0.0
START FLOW CONTROL	3019109A	10159	0.0
OIL/FUEL HEATER	10552	463	0.0
COMP. BLEED VALVE	3100829-03	3E630	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.