



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-21	TSN:	6,157	TSO:	2,685	W/O#:	6009
PCE:	24608	CSN:	6,769	CSO:	2,285	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1B153	6,769	12,231
Disk, 2 nd Stg.	3013712	6B145	6,769	17,231
Disk, 3 rd Stg.	3011713	5B991	6,769	18,231
Impeller	3013176	9A300	3,948	15,052
Disk, CT	3013411	1B477	6,769	9,231
PT Disk, 1 st Stg.	3022412	8A345	6,892	13,108

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002AE	1990858	448
FUEL PUMP	025323-101-02	7977	2,685.1
FUEL CONTROL UNIT	3244745-2	A75011	2,744.4
OIL/FUEL HEATER	10552E	WA11876	2,685.1
COMP. BLEED VALVE	3100829-03	1A279	2,685.1

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.