



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	11,379.3	TSO:	0.0	W/O#:	6303
PCE:	42671	CSN:	18,007	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	85B653	6,518	12,482
Disk, 2 nd Stg.	3013712	9L564	6,370	17,630
Disk, 3 rd Stg.	3011713	7L970	5,524	19,476
Impeller	3013176	TBA	9,225	9,775
Disk, CT	3013411	A001C4HC	5,798	10,202
PT Disk, 1 st Stg.	3022412	1M820	3,312	16,688

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-022AE	2700405	0.0
FUEL PUMP	025323-101-03	10375	0.0
FUEL CONTROL UNIT	3049625-02	C7272	0.0
START FLOW CONTROL	25234-3	14266	0.0
OIL/FUEL HEATER	10552E	WA7084	0.0
COMP. BLEED VALVE	3029742A	TBA	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.