



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	6,256.0	TSO:	0.0	W/O#:	6196
PCE:	14199	CSN:	N/A	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	18A895	2,059	16,941
Disk, 2 nd Stg.	3013712	42A477	4,306	19,694
Disk, 3 rd Stg.	3011713	42A493	3,806	21,194
Impeller	3013176	7D364	2,980	16,020
Disk, CT	3013411	41A660	4,678	11,322
PT Disk, 1 st Stg.	3022412	27A941	2,706	17,294

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-A	TBA	0.0
FUEL PUMP	025323-101	6339	0.0
FUEL CONTROL UNIT	2524440-7-6	A59530	0.0
START FLOW CONTROL	3019109B	TBA	0.0
OIL/FUEL HEATER	10552E	51147	0.0
COMP. BLEED VALVE	3100829-03	9W467	0.0
IGNITION EXITER	30321678	6262	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.