



11557 Hwy. 359
Mathis, Texas 78368
P.O. Box 146
Tynan, Texas 78391

361.547.3386
fax 361.547.7273
www.PT6A.aero

RECOMMENDED SERVICE INTERVALS

This information is for informational purposes only and ATS makes no representations about the accuracy or completeness of these guidelines.

You are encouraged to consult the appropriate Service Bulletins and Engine Maintenance Manuals for detailed recommendations and approvals.

MODEL	HSI (hr)	TBO (hr)
PT6A-6	1800	3600
PT6A-11	1800	3600
PT6A-11AG	1500	3000
PT6A-15AG	1500	3000
PT6A-20	1800	3600
PT6A-20A	1800	3600
PT6A-21	1800	3600
PT6A-25	1500	3000
PT6A-25A	1500	3000
PT6A-25C	1500	3000
PT6A-27	1800	3600
PT6A-28	1800	3600
PT6A-34	1500	4000
PT6A-34AG	1750	3500
PT6A-34B	1800	3600
PT6A-35	1800	3600
PT6A-36	1500	4000
PT6A-38	1000	2000
PT6A-110	1800	3600
PT6A-112	1800	3600
PT6A-114	1800	3600
PT6A-114A	1800	3600
PT6A-121	1800	3600
PT6A-135	1800	3600
PT6A-135A	1800	3600
PT6A-41	1250	2500
PT6A-41 *	1500	3000
PT6A-41 **	1800	3600

MODEL	HSI (hr)	TBO (hr)
PT6A-42	1500	3000
PT6A-42 ***	1800	3600
PT6A-42A	1800	3600
PT6A-45A	1500	4500
PT6A-45B	1500	4500
PT6A-45R	1500	4500
PT6A-50	1500	5500
PT6A-60A	1800	3600
PT6A-60AG	1500	3000
PT6A-61	1800	3600
PT6A-62	1500	3000
PT6A-64	1500	3000
PT6A-65AG	1500	3000
PT6A-65AR	2000	6000
PT6A-65B	2000	6000
PT6A-65R	2000	6000
PT6A-66	1500	3000
PT6A-66A	1500	3000
PT6A-67	1500	3000
PT6A-67A	1500	3000
PT6A-67AF	1500	3000
PT6A-67AG	1500	3000
PT6A-67B	1750	3500
PT6A-67D	2000	6000
PT6A-67R	2000	6000
PT6A-67T	1500	3000
PT6A-68	2250	4500
PT6A-68B	2250	4500
PT6A-68C	2250	4500

* POST-SB3075, POST-SB3089, POST-SB3097, PRE-SB3360

** POST-SB3089, POST-SB3097, POST-SB3360

*** POST-SB3360