



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-135A	TSN:	7,933.5	TSO:	0.0	W/O#:	6722
PCE:	92630	CSN:	8,182	CSO:	0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	7K482	8,182	10,818
Disk, 2 nd Stg.	3013712	8L230	8,182	15,818
Disk, 3 rd Stg.	3011713	6L639	8,182	16,818
Impeller	3027798	7F942	8,802	10,198
Disk, CT	3024211	5L776	8,182	7,818
PT Disk, 1 st Stg.	3022312	7K747	8,182	21,818

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-025	2482251	0.0
FUEL PUMP	025323-101-03	9366	0.0
FUEL CONTROL UNIT	3244897-4	C65970	0.0
OIL/FUEL HEATER	1052E	963	0.0
COMP. BLEED VALVE	3100829-03	7D131	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.