



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-27/-28</b>	TSN:	<b>16,072.5</b>	TSO:	<b>0.0</b>	W/O#:	<b>7291</b>
PCE:	<b>PG0113</b>	CSN:	<b>27,042</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	4K707	9,076	9,924
Disk, 2 <sup>nd</sup> Stg.	3013712	7H605	9,076	14,924
Disk, 3 <sup>rd</sup> Stg.	3011713	7H967	9,076	15,924
Impeller	3013176	6B224	6,940	12,060
Disk, CT	3013411	TBA	11,000	5,000
PT Disk, 1 <sup>st</sup> Stg.	3022412	4A410	7,433	12,567

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1480388	0.0
FUEL PUMP	025323-101-03	13284	0.0
FUEL CONTROL UNIT	2524440-7-6	A74840	0.0
START FLOW CONTROL	3019109	13904	0.0
OIL/FUEL HEATER	10552E	WA6368	0.0
COMP. BLEED VALVE	3100829-03	A-4496	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.