



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	GG: 12,313.4 PS: 13,715.5	TSO:	GG: 3,341.7 PS: 1,139.5	W/O#:	<b>9109</b>
PCE:	<b>42417</b>	CSN:	GG: 19,161 PS: 21,929	CSO:	GG: 4,159 PS: 1,944	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	77B116	16,247	2,753
Disk, 2 <sup>nd</sup> Stg.	3013712	8L235	21,563	2,437
Disk, 3 <sup>rd</sup> Stg.	3011713	1L248	21,563	3,437
Impeller	3013176	8H566	16,247	2,753
Disk, CT	3013411	A4592	14,678	1,322
PT Disk, 1 <sup>st</sup> Stg.	3022412	26B052	19,561	439

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003-01	142554	1,139.5
FUEL PUMP	025323-101-03	12170	2,634.2
FUEL CONTROL UNIT	2524440-7-6	A25771	1,334.1
START FLOW CONTROL	3019109	7885	1,436.0
OIL/FUEL HEATER	10552E	695	4,435.4
COMP. BLEED VALVE	3100829-03	A34389	3,341.7

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock