



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet

PT6A:	-34	TSN:	GG: 11,976.1 PS: 10,966.8	TSO:	GG: 0.0 PS: 0.0	W/O#:	9179
PCE:	51700	CSN:	GG: 11,853 PS: N/A	CSO:	GG: 0.0 PS: 0.0	TSHS:	0.0

Life Limited Part (LLP) Listing

	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	4K707	9,076	9,924
Disk, 2 nd Stg.	3013712	7H605	9,076	14,924
Disk, 3 rd Stg.	3011713	7H967	9,076	15,924
Impeller	3013176	1A531	11,583	7,417
Disk, CT	3013411	3A963	11,706	4,294
PT Disk, 1 st Stg.	3022412	3A373	9,919	10,081

Key: TBA = To be assigned, N/A = Not Applicable

Accessories

	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	11447245	0.0
FUEL PUMP	386101-5	1473	0.0
FUEL CONTROL UNIT	2524440-9	A25492	0.0
START FLOW CONTROL	25234-2	11085	0.0
OIL/FUEL HEATER	10552E	229	0.0
COMP. BLEED VALVE	3100829-03	8C426	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.