



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-42</b>	TSN:	<b>10,572.3</b>	TSO:	<b>0.0</b>	W/O#:	<b>6985</b>
PCE:	<b>93030</b>	CSN:	<b>12,230</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3041501	98A238	5,364	24,636
Disk, 2 <sup>nd</sup> Stg.	3023112	A2989	9,616	10,384
Disk, 3 <sup>rd</sup> Stg.	3023113	B0661	9,616	10,384
Impeller	3017463	9A877	12,230	7,770
Disk, CT	3049291-01	A000MK9C	3,714	6,286
PT Disk, 1 <sup>st</sup> Stg.	3029312	5W632	8,424	21,576
PT Disk, 2 <sup>nd</sup> Stg.	3029313	TBA	7,535	22,465

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-024-01	1746573	0.0
FUEL PUMP	025323-300-03	6655	0.0
FUEL CONTROL UNIT	3244768-13	A69188	0.0
OIL/FUEL HEATER	10585K-G-H-J	635	0.0
COMP. BLEED VALVE	3100922-05	9F630	0.0
COMP. BLEED VALVE	3100923-03	2F200	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: Post SB 3360  
 All engines ship FOB ATS dock.