



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-42</b>	TSN:	<b>8,696.5</b>	TSO:	<b>0.0</b>	W/O#:	<b>6921</b>
PCE:	<b>94620</b>	CSN:	<b>9,338</b>	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3040501	57A737	9,338	20,662
Disk, 2 <sup>nd</sup> Stg.	3023112	66A952	9,338	10,662
Disk, 3 <sup>rd</sup> Stg.	3023113	68A030	9,338	10,662
Impeller	3036793	6E924	9,338	10,662
Disk, CT	3049291-01	A001480K	3,221	6,779
PT Disk, 1 <sup>st</sup> Stg.	3029312	66A283	9,338	20,662
PT Disk, 2 <sup>nd</sup> Stg.	3029313	63A622	9,338	20,662

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-024-01	1818633	0.0
FUEL PUMP	025323-300	10149	0.0
FUEL CONTROL UNIT	3244768-13	B12756	0.0
OIL/FUEL HEATER	10585J	WA2599	0.0
COMP. BLEED VALVE	3100922-05	4K389	0.0
COMP. BLEED VALVE	3100923-02	3K056	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: Post SB 3360  
 All engines ship FOB ATS dock.