



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-65AR</b>	TSN:	GG: 6,806.7 PS: 7,120.4	TSO:	<b>0.0</b>	W/O#:	<b>6568</b>
PCE:	<b>97474</b>	CSN:	GG: 5,970 PS: 6,460	CSO:	<b>0.0</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3037101	64B798	453	23,547
Shaft Comp. Rotor	3037277	16A961	5,970	9,030
Disk, 2 <sup>nd</sup> Stg.	3036802	4X293	16,913	7,087
Disk, 3 <sup>rd</sup> Stg.	3036803	11A427	16,139	7,861
Disk 4 <sup>th</sup> Stg.	3036804	14A058	16,139	7,861
Impeller	3036794	5D352	5,970	18,030
Disk, CT	3040311	19A464	5,970	9,030
PT Disk, 1 <sup>st</sup> Stg.	3029312	8Y640	6,460	23,540
PT Disk, 2 <sup>nd</sup> Stg.	3029313	15A386	6,460	23,540

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-034	2169973G	0.0
FUEL PUMP	30338086	2101	0.0
FUEL CONTROL UNIT	8061-329	1998638	0.0
OIL/FUEL HEATER	10585H	5025	0.0
COMP. BLEED VALVE	3123126-01	310932	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.