



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-65B	TSN:	GG: 13,544.2 PS: 8,290.5	TSO:	GG: 0.0 PS: 3,438.8	W/O#:	9212
PCE:	GG: 32580 PS: 97432-100	CSN:	GG: 20,399 PS: 8,030	CSO:	GG: 0.0 PS: 2,929	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Shaft, Comp. Rotor	3043092	10B714	5,812	18,188
Disk, 1 st Stg.	3037101	64B798	453	23,547
Disk, 2 nd Stg.	3036802	4X293	16,913	7,087
Disk, 3 rd Stg.	3036803	11A427	16,139	7,861
Disk, 4 th Stg.	3036804	14A058	16,139	7,861
Impeller	3036794	5D352	5,970	18,030
Disk, CT	3040311	A002X0MD	1,261	13,739
PT Disk, 1 st Stg.	3029312	9Y822	7,985	22,015
PT Disk, 2 nd Stg.	3029313	9Y465	7,985	22,015

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-310	TBA	0.0
FUEL PUMP	399701-5	0745	0.0
FUEL CONTROL UNIT	8061-328	11451987	0.0
OIL/FUEL HEATER	10585K	200	0.0
COMP. BLEED VALVE	3117010-01	5X271	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.