



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet

PT6A:	-34	TSN:	GG: 12,488.8 PS: 13,715.5	TSO:	GG: 3,517.1 PS: 1,139.5	W/O#:	TBA
PCE:	42417	CSN:	GG: 19,372 PS: 21,929	CSO:	GG: 4,340 PS: 1,944	TSHS:	0.0

Life Limited Part (LLP) Listing

	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	77B116	16,458	2,542
Disk, 2 nd Stg.	3013712	8L235	21,774	2,226
Disk, 3 rd Stg.	3011713	1L248	21,774	3,226
Impeller	3013176	8H566	16,458	2,542
Disk, CT	3013411	A4592	14,889	1,111
PT Disk, 1 st Stg.	3022412	26B052	19,561	439

Key: TBA = To be assigned, N/A = Not Applicable

Accessories

	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-003-01	142554	1,139.5
FUEL PUMP	025323-101-03	12170	2,809.6
FUEL CONTROL UNIT	3244777-5-3-2	TBA	TBA
START FLOW CONTROL	3019109	7558	1,611.4
OIL/FUEL HEATER	10552E	695	4,610.8
COMP. BLEED VALVE	3100829-03	7C481	175.4

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.