



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

| <b>Engine Rotor Sheet</b> |              |      |                          |      |            |       |             |
|---------------------------|--------------|------|--------------------------|------|------------|-------|-------------|
| PT6A:                     | <b>-65B</b>  | TSN: | GG-6,806.7<br>PS-7,120.4 | TSO: | <b>0.0</b> | W/O#: | <b>6568</b> |
| PCE:                      | <b>97474</b> | CSN: | GG-5,970<br>PS-6,460     | CSO: | <b>0.0</b> | TSHS: | <b>0.0</b>  |

| <b>Life Limited Part (LLP) Listing</b> |         |        |          |           |
|--|---------|--------|----------|-----------|
|  | P/N     | S/N    | Cycles   |           |
|  |         |        | Consumed | Remaining |
| Hub, 1 <sup>st</sup> Stg.              | 3037101 | 64B798 | 453      | 23,547    |
| Shaft Comp. Hub                        | 3037277 | 16A961 | 5,970    | 9,030     |
| Disk, 2 <sup>nd</sup> Stg.             | 3036802 | 4X293  | 16,913   | 7,087     |
| Disk, 3 <sup>rd</sup> Stg.             | 3036803 | 11A427 | 16,139   | 7,861     |
| Disk, 4 <sup>th</sup> Stg.             | 3036804 | 14A058 | 16,139   | 7,861     |
| Impeller                               | 3036794 | 5D352  | 5,970    | 18,030    |
| Disk, CT                               | 3040311 | 19A464 | 5,970    | 9,030     |
| PT Disk, 1 <sup>st</sup> Stg.          | 3029312 | 8Y640  | 6,460    | 23,540    |
| PT Disk, 2 <sup>nd</sup> Stg.          | 3029313 | 15A386 | 6,460    | 23,540    |

Key: TBA = To be assigned, N/A = Not Applicable

| <b>Accessories</b> |            |          |     |
|--------------------|------------|----------|-----|
|                    | P/N        | S/N      | TSO |
| PROPELLER GOVERNOR | 8210-310   | 12393502 | 0.0 |
| FUEL PUMP          | 3040760B   | 005761   | 0.0 |
| FUEL CONTROL UNIT  | 8061-328   | 12206463 | 0.0 |
| FLOW DIVIDER       | 26130-2    | TBD      | 0.0 |
| OIL/FUEL HEATER    | 10585H     | 5025     | 0.0 |
| COMP. BLEED VALVE  | 3123126-01 | 310932   | 0.0 |

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.