



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-28	TSN:	GG: 7,910.2 PS: 7,853.8	TSO:	GG: 3,159.2 PS: 3,102.8	W/O#:	N/A
PCE:	51990	CSN:	GG: 6,366 PS: 6,760	CSO:	GG: 2,944 PS: 3,338	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	06B777	6,366	12,634
Disk, 2 nd Stg.	3013712	09B672	6,366	17,634
Disk, 3 rd Stg.	3011713	09B520	6,366	18,634
Impeller	3013176	05A595	6,366	12,634
Disk, CT	3013411	08B984	6,366	9,634
PT Disk, 1 st Stg.	3022412	08B367	6,760	13,240

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	T8210-003U	2168073	4,447.2
FUEL PUMP	025323-101-3	7072D	1,662.7
FUEL CONTROL UNIT	2524440-9	C7179	1,662.7
START FLOW CONTROL	3019109	11939	1,662.7
OIL/FUEL HEATER	10552E	2918	1,662.7
COMP. BLEED VALVE	3100829-03	3H153	629.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.