



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-67R	TSN:	21,857.3	TSO:	1,391.8	W/O#:	10113
PCE:	106033	CSN:	30,691	CSO:	416	TSHS:	244.4

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Shaft, Comp. Rotor	3043092	PKAAA195817	4,229	19,771
Hub, 1 st Stg.	3037001	EAAA000K712	6,035	17,695
Disk, 2 nd Stg.	3040942	51B153	15,919	8,081
Disk, 3 rd Stg.	3040933	66B467	9,467	14,533
Disk, 4 th Stg.	3040944	69B196	9,467	14,533
Impeller	3036898	7H083	9,467	14,533
Disk, CT	3040911	50A320	3,929	4,071
PT Disk, 1 st Stg.	3037312	24B447	12,733	2,267
PT Disk, 2 nd Stg.	3037313	22B954	12,727	2,273

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-409	17917539	1,391.8
FUEL PUMP	399701-5	2109	1,391.8
FUEL CONTROL UNIT	8063-023	2123091	1,391.8
THERMOSTATIC BY-PASS	3024996	PWC98A404	1,391.8
OIL/FUEL HEATER	10585K-FGH	221	244.4
COMP. BLEED VALVE	3123532-01	51A938	1,391.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.