



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>10,838.1</b>	TSO:	<b>3,872.1</b>	W/O#:	<b>10353</b>
PCE:	<b>52151</b>	CSN:	<b>12,685</b>	CSO:	<b>5,514</b>	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	9C931	12,685	6,315
Disk, 2 <sup>nd</sup> Stg.	3013712	7D533	12,685	11,315
Disk, 3 <sup>rd</sup> Stg.	3011713	6C296	12,685	12,315
Impeller	3013176	7A461	12,685	6,315
Disk, CT	3013411	A0001P9D	14,941	1,059
PT Disk, 1 <sup>st</sup> Stg.	3022412	7C695	12,685	7,315

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	983056	656.3
FUEL PUMP	025323-101-02	7979	3,872.1
FUEL CONTROL UNIT	252444-0-7-6	A25113	2,856.8
START FLOW CONTROL	3019109	13301	3,872.1
OIL/FUEL HEATER	10552E	1129	3,872.1
COMP. BLEED VALVE	3100829-03	8F793	3,872.1

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.