



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	6,573.5	TSO:	2,635.3	W/O#:	TBA
PCE:	PC0883	CSN:	7,437	CSO:	3,091	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	70B273	7,437	11,563
Disk, 2 nd Stg.	3013712	A000T5MK	7,437	16,563
Disk, 3 rd Stg.	3011713	A000T5NF	7,437	17,563
Impeller	3027798	8H029	7,437	11,563
Disk, CT	3013411	A000RWPE	7,437	8,563
PT Disk, 1 st Stg.	3026812	A000T5X6	7,437	12,563

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	13039152	2,635.3
FUEL PUMP	3034792	0603	2,635.3
FUEL CONTROL UNIT	3244809-8	C25593	3,592.9
FLOW DIVIDER	3019906D	20615	2,635.3
OIL/FUEL HEATER	3032710	WA16602	2,635.3
COMP. BLEED VALVE	3049038-03	4387	2,635.3

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.