



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	114A	TSN:	11998.3	TSO:	0.0	W/O#:	TBD
PCE:	PC1927	CSN:	22641	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	PAC0089	7,618	11,382
Disk, 2 nd Stg.	3013712	A0032AHX	7,926	16,074
Disk, 3 rd Stg.	3011713	A0032AKH	8,524	15,476
Impeller	3027798	3F060	12311	6,689
Disk, CT	3013411	CRAZAFDN125	6645	9,355
PT Disk, 1 st Stg.	3026812	A00007DD	5796	14,231

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1715639	0.0
FUEL PUMP	702801-5	003830	0.0
FUEL CONTROL UNIT	3244897-4	C66804	0.0
FLOW DIVIDER/ DUMPVALVE	25536-4	L0454	0.0
OIL/FUEL HEATER	10552E	WA42618	0.0
COMP. BLEED VALVE	3019038-03	7656	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.