



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-27/-28	TSN:	GG: 31,277.4 PS: 17,619.9	TSO:	GG: 0.0 PS: 0.0	W/O#:	9890
PCE:	GG: 40630 PS: 40529-100	CSN:	GG: 56,650 PS: 20,818	CSO:	GG: 0.0 PS: 0.0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	1D815	11,129	7,871
Disk, 2 nd Stg.	3013712	3X086	10,564	13,436
Disk, 3 rd Stg.	3011713	2X156	10,564	14,436
Impeller	3013176	3C186	7,926	11,074
Disk, CT	3013411	A00010C6	3,368	12,632
PT Disk, 1 st Stg.	3022412	6345	12,533	7,467

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	2120759	0.0
FUEL PUMP	025323-101	3079	0.0
FUEL CONTROL UNIT	2524440-7-6	308481	0.0
FLOW DIVIDER	25234-2	8943	0.0
OIL/FUEL HEATER	UA525193-7	421	0.0
COMP. BLEED VALVE	3100829-03	3H153	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.