



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-67D	TSN:	21,174	TSO:	6,089.8	W/O#:	10796
PCE:	114043	CSN:	32,493	CSO:	9,154	TSHS:	545.4

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3039001	41B963	19,759	4,241
Disk, 2 nd Stg.	3040952	69B572	9,154	14,846
Disk, 3 rd Stg.	3040933	69B880	9,154	14,846
Disk, 4 th Stg.	3040944	70B392	9,154	14,846
Rotor Shaft	3043063	A000MW67	9,154	14,846
Impeller	3036898	7H444	9,154	14,846
Disk, CT	3040911	A0005W72	7,328	672
PT Disk, 1 st Stg.	3037312	A000P6HA	9,154	5,846
PT Disk, 2 nd Stg.	3037313	A000PNR4	9,154	5,846

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-410	11448781	1,491.9
FUEL PUMP	399701-5	0271	6,089.8
FUEL CONTROL UNIT	8063-005B	11892452	6,089.8
FLOW DIVIDER	26130-2	0440	6,089.8
OIL/FUEL HEATER	10585J	1020	6,089.8
COMP. BLEED VALVE	3123532-01	40A561	6,089.8

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.