



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	GG-29,652.5 PS-29,713.8	TSO:	<b>3,532.3</b>	W/O#:	<b>10304</b>
PCE:	GG-57031 PS-56398	CSN:	GG-40,538 PS-35,509	CSO:	<b>3,033</b>	TSHS:	<b>3,532.3</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	1R959	6,453	12,547
Disk, 2 <sup>nd</sup> Stg.	3013712	5R821	6,453	17,547
Disk, 3 <sup>rd</sup> Stg.	3011713	4R399	6,453	18,547
Impeller	3013176	5F985	6,389	12,611
Disk, CT	3013411	30A346	15,532	468
PT Disk, 1 <sup>st</sup> Stg.	3022412	10A422	7,316	12,684

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	TBA	TBA	0.0
FUEL PUMP	025323-101-03	446	0.0
FUEL CONTROL UNIT	TBA	TBA	0.0
START FLOW CONTROL	25234-2	7533	0.0
OIL/FUEL HEATER	10552E	1683	0.0
COMP. BLEED VALVE	3100829-03	48A676	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.  
 Ct blade life 3,532.3