



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	<b>2,882.3</b>	TSO:	<b>NA</b>	W/O#:	<b>TBA</b>
PCE:	<b>RB0078</b>	CSN:	<b>3,133</b>	CSO:	<b>NA</b>	TSHS:	<b>946.8</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	61B797	3,133	15,867
Disk, 2 <sup>nd</sup> Stg.	3013712	A000CW28	3,133	20,867
Disk, 3 <sup>rd</sup> Stg.	3011713	A000D3P4	3,133	21,867
Impeller	3013176	5H359	3,133	15,867
Disk, CT	3013411	A000CW28	3,133	12,867
PT Disk, 1 <sup>st</sup> Stg.	3026812	A000DBXB	3,133	16,867

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	3035927	12198692U	2,882.3
FUEL PUMP	3034794	1326	2,882.3
FUEL CONTROL UNIT	252440-9	C7172	0.0
START FUEL CONTROL	3019109	15318	2,882.3
OIL/FUEL HEATER	3032710	WA14577	2,882.3
COMP. BLEED VALVE	3100829-03	39A152	2,882.3

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.