



Airforce Turbine Service
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34AG	TSN:	6,350.07	TSO:	2,351.47	W/O#:	12284
PCE:	PH0179	CSN	Starts: 6,057 Flights: 14,121	CSO	Starts: 3,577 Flights: 6,067	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	9L004	3,298	15,702
Disk, 2 nd Stg.	3013712	9L384	10,201	13,799
Disk, 3 rd Stg.	3011713	9955	8,667	16,333
Impeller	3013176	A6649	5,347	13,653
Disk, CT	3013411	4HC05	12,010	3,990
PT Disk, 1 st Stg.	3026812	A00135L8	6,861	17,139

Key: TBA = To be assigned, N/A = Not Applicable

Accessories			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-002-01	1440198	486.03
FUEL PUMP	025323-101-03	2367	2,351.47
FUEL CONTROL UNIT	2524440-7-3-2	A48241	2,232.7
START FLOW CONTROL	25234-3	14232	2,351.4
OIL/FUEL HEATER	10552E	WA29048	2,351.4
COMP. BLEED VALVE	3100829-03	2C225	2,351.4

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.