



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet

PT6A:	-114A	TSN:	22,326.9	TSO:	764.0	W/O#:	12293
PCE:	19177	CSN:	20,595	CSO:	753	TSHS:	764.0

Life Limited Part (LLP) Listing

	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	24A827	17,900	1,100
Disk, 2 nd Stg.	3013712	3B669	21,341	2,659
Disk, 3 rd Stg.	3011713	4T445	23,009	1,991
Impeller	3027798	TXA1A4580	18,561	439
Disk, CT	3013411	64A251	15,094	906
PT Disk, 1 st Stg.	3026812	1T936	19,703	297

Key: TBA = To be assigned, N/A = Not Applicable

Accessories

	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	2244559	764.0
FUEL PUMP	702801-5	003375	764.0
FUEL CONTROL UNIT	3244897-4	C65589	764.0
FLOW DIVIDER	25536-4	9959559351	764.0
OIL/FUEL HEATER	10552E	WA20811	764.0
COMP. BLEED VALVE	540-1307-4	3489	764.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.