



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet

PT6A:	-34	TSN:	GG: 23,800.4 PS: 22,805.5	TSO:	GG: 0.0 PS: 1,270.5	W/O#:	TBA
PCE:	GG: 56953 PS: 56770-100	CSN:	GG: 28,535 PS: 27,952	CSO:	GG: 0 PS: 2,118	TSHS:	0.0

Life Limited Part (LLP) Listing

	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	34B657	12,967	6,033
Disk, 2 nd Stg.	3013712	36B989	12,176	11,824
Disk, 3 rd Stg.	3011713	33B687	12,176	12,824
Impeller	3013176	8F177	12,163	6,837
Disk, CT	3013411	8X130	13,490	2,510
PT Disk, 1 st Stg.	3022412	15B234	10,055	9,945

Key: TBA = To be assigned, N/A = Not Applicable

Accessories

	P/N	S/N	TSO
PROP GOVERNOR	8210-003-01	1451926	0.0
FUEL PUMP	025323-101	TBD	0.0
FUEL CONTROL UNIT	3244777	TBD	0.0
START FLOW CONTROL	3019109	TBD	0.0
OIL/FUEL HEATER	10552E	TBD	0.0
COMP. BLEED VALVE	3100829-03	TBD	0.0

Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.

Comments: All engines ship FOB ATS dock.