



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
P.O. Box 146 Tynan, TX 78391
Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-114A	TSN:	7,196.9	TSO:	0.0	W/O#:	11489
PCE:	PC1319	CSN:	7,286	CSO:	0	TSHS:	0.0

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	RWA38A780	7,286	11,714
Disk, 2 nd Stg.	3013712	A002107W	7,286	16,714
Disk, 3 rd Stg.	3011713	A00214YC	7,286	17,714
Impeller	3027798	EAAA000E104	7,286	11,714
Disk, CT	3013411	CRAZAESI270	2,490	13,510
PT Disk, 1 st Stg.	3026812	A0021R76	7,286	12,714
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-002-01	14773834	0.0
FUEL PUMP	702801-5	001344	0.0
FUEL CONTROL UNIT	3244897-4	C65920	0.0
FLOW DIVIDER	25536-4	9959512782	0.0
OIL/FUEL HEATER	10552E	WA23967	0.0
COMP. BLEED VALVE	540-1407-4	5026	0.0
Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.			

Comments: All engines ship FOB ATS dock.