



Airforce Turbine Service
www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368
 P.O. Box 146 Tynan, TX 78391
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

Engine Rotor Sheet							
PT6A:	-34	TSN:	GG: 21,713.4 PS: 27,578.3	TSO:	GG: 5,912.8 PS: 7,219.0	W/O#:	TBA
PCE:	GG: 56061 PS: 56241-100	CSN:	GG: 25,295 PS: 36,003	CSO:	GG: 7,301 PS: 8,296	TSHS:	UNKNOWN

Life Limited Part (LLP) Listing				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 st Stg.	3013111	A0341	17,488	1,512
Disk, 2 nd Stg.	3013712	37B489	6,946	17,054
Disk, 3 rd Stg.	3011713	5016	16,525	8,475
Impeller	3013176	3C104	17,713	1,287
Disk, CT	3013411	A8006	13,516	2,484
PT Disk, 1 st Stg.	3022412	35A806	17,701	2,299
Key: TBA = To be assigned, N/A = Not Applicable				

Accessories			
	P/N	S/N	TSO
PROP GOVERNOR	8210-003	TBD	TBD
FUEL PUMP	025323-101-03	TBD	TBD
FUEL CONTROL UNIT	3244834-1	TBD	TBD
START FLOW CONTROL	3019109	TBD	TBD
OIL/FUEL HEATER	10552E	TBD	TBD
COMP. BLEED VALVE	3100829-03	TBD	TBD
Key: TBA = To be assigned, N/A = Not Applicable Serial numbers are subject to change.			

Comments: All engines ship FOB ATS dock.