



**Airforce Turbine Service**  
 www.PT6A.aero

11557 Hwy 359 Mathis, TX 78368  
 P.O. Box 146 Tynan, TX 78391  
 Ph: (361) 547-3386 Fx: (361) 547-7273

ATS Form# 1024

<b>Engine Rotor Sheet</b>							
PT6A:	<b>-34</b>	TSN:	GG: 25,990.3 PS: 28,113.2	TSO:	GG: 0.0 PS: 0.0	W/O#:	<b>TBD</b>
PCE:	GG: 56281 PS: 56760-100	CSN:	GG: 31,653 PS: 36,436	CSO:	GG: 0 PS: 0	TSHS:	<b>0.0</b>

<b>Life Limited Part (LLP) Listing</b>				
	P/N	S/N	Cycles	
			Consumed	Remaining
Hub, 1 <sup>st</sup> Stg.	3013111	5082	16,150	2,850
Disk, 2 <sup>nd</sup> Stg.	3013712	A0011X3T	21,670	2,330
Disk, 3 <sup>rd</sup> Stg.	3011713	A0011BXT	21,670	3,330
Impeller	3013176	6C040	16,555	2,445
Disk, CT	3013411	A001XX53	14,739	1,261
PT Disk, 1 <sup>st</sup> Stg.	3026812	8A113	14,595	2,331

Key: TBA = To be assigned, N/A = Not Applicable

<b>Accessories</b>			
	P/N	S/N	TSO
PROPELLER GOVERNOR	8210-004-01	1483007	0.0
FUEL PUMP	025323-101-03	R1240	0.0
FUEL CONTROL UNIT	2524440-9-8-6	A7031	0.0
START FUEL CONTROL	25234-5	15438	0.0
OIL/FUEL HEATER	10552E	1014	0.0
COMP. BLEED VALVE	3029174	A34016	0.0

Key: TBA = To be assigned, N/A = Not Applicable

Comments: All engines ship FOB ATS dock.